

METALEA

3D LASER CUT MODELS








To create the best connections




helpful for assembly






Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Insertion Fold Insertion holes tabs are lines can

inserted be seen and then as shown folded here

Metal sheets 0 49 83 854448



4246 In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

