


# METAL EARTH™

## 3D LASER CUT MODELS



It is highly recommended that you visit  
[www.fascinations.com/metalearth360/mms371](http://www.fascinations.com/metalearth360/mms371)  
 to see the completed model before assembling your own




mms371

### To create the best connections

Insert tab and bend 90 degrees for most visible areas

Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Legends:


Engraved side

Non-engraved side


Attention point

Insertion tabs are inserted and then folded

Fold lines can be seen as shown here




### Metal sheets




In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

### Assembly Flow Chart







TIP: see the online product view for the actual look of this part

