
METAL EAR

3D LASER CUT MODELS



It is highly recommended that you visit www.fascinations.com/metalearth360/mms300 to see the completed model before assembling your own






mms300

To create the best connections

Insert tab and bend 90 for most visible areas



Fold

here

lines can

be seen


as shown

Insertion holes Insertion tabs are inserted and then folded





Insert tab and twist 90 degrees is best in some areas to ensure



23 42 35 47 36 6 Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed



