

# Taipei 101




It is highly recommended that you visit  
[www.fascinations.com/iconx360/icx007](http://www.fascinations.com/iconx360/icx007)  
 to see the completed model before assembling your own

**ICONX**  
 3D METAL MODEL KITS

FASCINATIONS, INC.  
 Seattle, Washington, USA

ICX007





## TO CREATE THE BEST CONNECTIONS


● Insert tab into slot and  
 bend 90 degrees



▲ Insert tab into slot and  
 twist 90 degrees




## METAL SHEETS




**!** In order to avoid possible injury from sharp edges, please carefully discard  
 the metal sheet after parts have been removed.

Go to [www.fascinations.com/iconx360/icx007](http://www.fascinations.com/iconx360/icx007) to see the zoomable PDF version of this instruction sheet




## ASSEMBLY STEPS


### Step 1




### Step 2




### Step 3




### Step 4




### Step 5




### Step 6




### Step 7




## Step 8




## Step 9




## Step 10




## Step 11



## Step 12



## Step 13



## Step 14

